



## **APPENDIX D**

Distance-Drawdown Analyses Plots


**Figure D-1**  
**Distance Versus *Trend-Corrected* Drawdown Response During the EW-5 Pumping Test**  
**Observation Wells Screened Within the LWBM**  
Newmark Groundwater Contamination Superfund Site




**Figure D-2**  
**Distance Versus *Trend-Corrected* Drawdown Response During the EW-4 Pumping Test**  
**Observation Wells Screened Within the LWB**  
Newmark Groundwater Contamination Superfund Site




**Figure D-3**  
**Distance Versus *Uncorrected* Drawdown Response During the EW-3 Pumping Test**  
**Observation Wells Screened Within the LWBM**  
Newmark Groundwater Contamination Superfund Site



**Figure D-4**  
**Distance Versus *Trend-Corrected* Drawdown Response During the EW-2 Pumping Test**  
**Observation Wells Screened Within the LWBM**  
Newmark Groundwater Contamination Superfund Site



**Figure D-5**  
**Distance Versus *Uncorrected* Drawdown Response During the EW-1 Pumping Test**  
**Observation Wells Screened Within the LWBM**  
Newmark Groundwater Contamination Superfund Site



**Figure D-6**  
**Distance Versus *Uncorrected* Drawdown Response During the WD#15 Pumping Test**  
Newmark Groundwater Contamination Superfund Site

